# **SAFETY RECALL NOTICE**



Bombardier Recreational Products Inc. 565 de la Montagne Street Valcourt, Québec, Canada J0E 2L0

www.brp.com

Date: October 27, 2010

Re: Can-Am<sup>™</sup> DS 450<sup>™</sup> Speedometer Inaccuracy (CE MODELS ONLY)

2009 DS 450 CE 2009 DS 450 X™ CE 2009 DS 450 X mx CE

Dear Can-Am ATV Dealer / Distributor,

# This notice is sent to you in accordance with the requirements of the General Product Safety Direction of the European Community and other applicable laws.

#### What is the reason for this notice?

Bombardier Recreational Products Inc. ("BRP") is conducting a voluntary safety recall of certain 2009 Can-Am ATV DS 450 CE models, as specified in the attached Safety Campaign Bulletin.

#### What is the potential problem?

Involved vehicles have inaccurate speedometer reading (30% less than actual speed). This situation could result in vehicle being driven at illegal speeds and could alter the judgment of the driver in some riding conditions. This condition may increase the risk of a crash with injury or death.

#### What will BRP do?

BRP is sending a Safety Recall letter to all known registered owners of these vehicles. This letter urges the owners to contact their authorized BRP Can-Am ATV dealer to have their vehicle serviced. BRP also posted this notice and attached Safety Campaign Bulletin on its BOSSWeb dealer website (www.bossweb.brp.com) and on its public website (www.can-am.brp.com).

#### What should you do?

- 1. Do not sell or deliver any involved ATV until the repair has been completed.
- 2. Contact all of your customers who purchased an affected model. You must inform them about the foregoing and advise them to make an appointment to update the speedometer calibration. If they choose to ride their vehicle prior to this service, urge them to be aware of this condition.
- 3. Follow all instructions applicable to model as provided in the attached Safety Campaign Bulletin.

#### If you have questions about this notice:

• Please contact your local distributor or regional office which can be found at www.brp.com.

We apologize for any inconvenience this may cause you. Thank you for your immediate attention to this matter.

Sincerely, After-Sales Service Department

Ski-Doo Lynx Sea-Doo Evinrude Johnson Rotax Can-Am



 $\Delta$  WARNING: All involved customers must be notified, all involved units must be corrected as per instructions herein.

### Campaign no.: 2009-0009

October 27, 2010

Subject: Can-Am<sup>™</sup> DS 450<sup>™</sup> Speedometer Inaccuracy (CE MODELS ONLY)

No. 2009-8 REVISION 1

December 14, 2010

YEAR	MODEL	MODEL NUMBER	SERIAL NUMBER
	DS 450 <b>CE</b>	3F9G / 3F9F	
2009	DS 450 X™ <b>CE</b>	3G9D	See Attached List
	DS 450 X mx <b>CE</b>	3H9C	
	<ul> <li>Underlined text(s) between arrows is (a</li> </ul>	are) modified element(s) to the original pu	ublication.

## PROBLEM

Involved vehicles have inaccurate speedometer reading (30% less than actual speed).

This situation could result in vehicle being driven at illegal speeds and could alter the judgment of the driver in some riding conditions. This condition may increase the risk of a crash with injury or death.

# SOLUTION

Update speedometer calibration.

▶ On some vehicles, all the multifunction gauge settings and registered information may reset during the update.

This includes:

- <u>Odometer (total distance travelled by the vehicle)</u>
- Language
- <u>– Cluster mode</u>
- <u>– Cluster units</u>
- <u>– Cluster racing</u>
- Cluster country.

At the end of the procedure, they must be set according to the vehicle usage. The customer must be advised of this situation. To prevent the loss of this information, it is reguested to print a B.U.D.S. report **BEFORE** beginning the update procedure.

Give the report to the customer for his own records and keep a copy for your records.

# PROCEDURE

## **Calibration File Download**

**NOTE:** Always use the latest B.U.D.S. version on your shop computer. At time of printing, the latest B.U.D.S. version is P2.3.31. It is available from the following web site: http://www.bossweb.brp.com.

1. On the internet, go to the BOSSWeb site:

#### WWW.BOSSWEB.BRP.COM

- 2. Under ComCenter drop down list, select: – DOCUMENT
- 3. In the menu, select:
- Document Type: DIAGNOSTIC SOFTWARE
- 4. Click on arrow and wait for results.

5. Select and download the following calibration update file:

### SPEEDOMETER UPDATE FILE 715 900 125.FC

**NOTE:** If your internet connection is not on your shop PC, save the file to a floppy diskette, a USB memory stick or a CD ROM to then copy it to your shop PC. Take note where you save the file, because you will browse for it.

## **B.U.D.S. Connection**

1. Connect vehicle to B.U.D.S. Refer to 2008 CAN-AM DS 450 EFI SHOP MANUAL — Subsection 02 under COMMUNICATION TOOLS AND B.U.D.S. SOFTWARE.

REQUIRED COMMUNICATION TOOLS
MPI-2 INTERFACE CARD (P/N 529 036 018)
MPI-2 DIAGNOSTIC CABLE (P/N 710 000 851)
B.U.D.S. KW2000 (500K) protocol



DS 450 EFI COMMUNICATION CONNECTOR (TYPICAL)

NOTE: Do not use D.E.S.S. POST INTERFACE (P/N 529 036 019).



DO NOT USE D.E.S.S. POST INTERFACE

## B.U.D.S. Database Update

- 1. Turn ignition key to ON.
- 2. Start B.U.D.S. and logon.
- 3. Ensure both USB and CAN lights of MPI-2 are green.
- 4. Ensure the status bar shows KW2000 (500K) with the number 2 to its right.



CONNECTION SUCCESSFUL — ECM AND MULTIFUNCTION GAUGE ARE CONNECTED

5. If the following message is displayed, it should disappear as soon as B.U.D.S. detects communication. If it remains displayed, click the button "Try active detection mode".



6. Click on *TOOLS* drop down list and select: – *UPDATE DATABASE...* 



### 7. Click on ADD UPDATE.

9			
Name	Date	Description	File Name
HY1911B8	2008-02-12	Overtemp Engine Limitation correction for first generation Production ECU	715 900 059.fc
HY1911B7	2008-02-12	Overtemp Engine Limitation correction for second generation Production ECU	715 900 059.fc
Outlander C18 709400830	2009-06-18	Outlander calibration for C18	715 900 070.fc
Renegade C18 709400831	2009-06-18	Renegade calibration for C18	715 900 070.fc
S01112C18_WITH	2009-06-18	Outlander Calibration + Software for C18	715 900 070.fc
S01112C18_WITH	2009-06-18	Renegade Calibration + Software for C18	715 900 070.fc
S01112C18_WITH	2009-07-02	Software and calibration update for ATV Outlander/Renegade as per Service Part - Boot mode	715 900 070 fc

TYPICAL

- 8. Locate the previously downloaded calibration update file and click *OPEN*.
- 9. Click "OK" when the confirmation message appears.
- 10. Click CLOSE in the "Update Database".

### ▶ Printing B.U.D.S. Report (Prior to Update)

The B.U.D.S. report must be printed **BEFORE** doing the update procedure. The report must be handed to the customer.

1. Click on PRINT button.



1. PRINT button

2. In the PAGES TO PRINT area, uncheck all selections except VEHICLE.

1→-	⊻ehicle	⊏ Kevs	F 5
, r	Monitoring	□ Eaults	E B

- 3. Keep this report for the customer.
- <u>4. Reprint or do a copy of the report for your</u> records.

### Vehicle Update

**NOTICE** Continuous power to the computer and to the vehicle ECM is mandatory during this operation.

- 1. Disable computer screen saver. Provide enough electrical supply to the computer to avoid interruptions.
- 2. Check vehicle battery voltage. The battery must be fully charged or use a power pack to have enough power.
- 3. In B.U.D.S. window, click on *READ DATA* button.



- 4. Click on *MODULE* drop down list and select:
  - Cluster
  - Update.
- <u>5.</u> ► Select the proper update.

<u>NAME</u>	<b>DESCRIPTION</b>
<u>Renegade NoClock</u> 03 12 10 715900115	DS 450 CE speed calibration for cluster without clock.
<u>Renegade RTC</u> <u>03 12 10 715900114</u>	DS 450 CE speed calibration for cluster with clock.

- 6. Click on OK button.
- 7. Confirm multifunction gauge update by clicking YES button.

NOTE: Depending which update has been selected, one of these 2 messages will be displayed. DS 450 CE speed calibration for cluster without clock 715900115 DS 450 CE speed calibration for cluster with clock 715900114 You are about to update the internal CLUSTER software. Make sure that interface power and connections are stable. The update may require several minutes. Do you want to proceed now? Comments DS 450 CE speed calibration for cluster without clock 715900115 No Yes vbq2009-008-103



**NOTICE** While the vehicle is updated, an hour glass will appear on the computer. The computer screen might also blank out or seem to be frozen. DO NOT TOUCH ANYTHING until the following message appears.

Update has been successfully transferred

8. Click on OK button.



NOTE: An automatic "Read Data" will be done.

- 9. Confirm that BRP Software Number is updated by selecting:
  - Module
  - Cluster
  - Information.

BRP SOFTWARE NUMBER 715 900 114 or 715 900 115

BRP Assembly Number:	710001983
BRP Software Number:	715900 <b>XXX</b>
Supplier Part Number:	556233
Serial Number:	000000000
Diagnosis Code Bytes:	03010300
Code Modification Fingerprint:	10/10/26 02010
Vehicle Model:	00000000
∨ehicle Serial Number (∨IN):	000000000000000000000000000000000000000
Customer Name:	DS450CE
Delivery Date:	101026
vbg2009-008-104_a	

TYPICAL

- 10. Click on Close button.
- 11. Select Setting page.
- 12. Select Cluster tab.
- 13. Set multifunction gauge parameters according to vehicle usage.

		Monitoring		
1 Clus	ster Language	3	4 Cluster F ☉ Star ← Rac	ndard

SET THE FOLLOWING PARAMETERS

- Cluster Language Cluster Mode
- 1. 2. 3. 4.
- <u>Cluster Units</u> <u>Cluster Racing</u> 5. Cluster Country

# NOTE: It is IMPORTANT to select CE in the Clus-

### ter Country area.

14. Select Vehicle page in B.U.D.S.

14.1 Click on Reset Service Info.

15. Click on WRITE DATA button.



WRITE DATA BUTTON

- 16. Click **YES** to confirm.
- 17. Click on **EXIT** button to end session.
- 18. Disconnect all cables and hardware from vehicle.

## **Speedometer Testing**

- 1. Turn ignition key to ON.
- 2. Ensure that speedometer works properly.

## ▶ B.U.D.S. Report for Customer

The B.U.D.S. report must be handed to the customer and a copy should be kept for the dealer records.

# WARRANTY

## **Vehicles Claiming**

Submit a warranty claim using the following information:

WARRANTY INFORMATION		
Campaign Number	2009-0009	
Claim Type	Campaign Claim	
Flat Rate	0.3 hour	

## **Claiming Procedure**

For claiming procedure, refer to the *DEALER/DIS-TRIBUTOR WARRANTY GUIDE*.

# SERIAL NUMBER LISTING OF INVOLVED VEHICLES

*Model: 3F9F* 000002 From 000136 to 000173

### Model: 3F9G

From 000001 to 000324

#### Model: 3G9D

From 002931 to 003284 From 003286 to 003296 From 003298 to 003308 From 003310 to 003420

#### Model: 3H9C

From 000798 to 000807 From 000833 to 000856 From 000919 to 001059

# **SAFETY RECALL NOTICE**



Bombardier Recreational Products Inc. 565 de la Montagne Street Valcourt, Québec, Canada J0E 2L0

www.brp.com

Date: October 27, 2010

Re: Can-Am<sup>™</sup> DS 450<sup>™</sup> Speedometer Inaccuracy (CE MODELS ONLY)

2009 DS 450 CE 2009 DS 450 X™ CE 2009 DS 450 X mx CE

Dear Can-Am ATV Owner,

This notice is sent to you in accordance with the requirements of the General Product Safety Direction of the European Community and other applicable laws.

#### What is the reason for this notice?

Bombardier Recreational Products Inc. ("BRP") is conducting a voluntary safety recall of certain 2009 Can-Am ATV DS 450 CE models. **Our records indicate that you are the owner of a potentially affected vehicle.** 

#### What is the potential problem?

Involved vehicles have inaccurate speedometer reading (30% less than actual speed). This situation could result in vehicle being driven at illegal speeds and could alter the judgment of the driver in some riding conditions. This condition may increase the risk of a crash with injury or death.

#### What should you do?

Call an authorized BRP Can-Am ATV dealer and make an appointment to have your vehicle serviced. *The dealer will perform this work at no charge to you*. Should you choose to ride your vehicle prior to this service, we urge you to be aware of this condition.

# If you have questions, please contact your authorized BRP dealer which can be found at www.brp.com.

This notice was mailed to you according to the most current information we have available. If you no longer own this vehicle or some information in this notice is incorrect, please inform your local BRP dealer at your earliest convenience.

We apologize for any inconvenience this may cause you, but we have taken this action in the interest of your safety. Thank you for your immediate attention to this matter.

Sincerely, After-Sales Service Department Bombardier Recreational Products Inc. Ski-Doo Lynx Sea-Doo Evinrude Johnson Rotax Can-Am