

CAUTION: All involved customers must be notified, all involved units must be corrected as per instructions herein.

Campaign no.: 2013–9

June 28th, 2013 Subject: Tire Label Replacement

No. **2013-5**

YEAR	MODEL	MODEL NUMBER	SERIAL NUMBER
2013	Commander™ Electric	6MDB/6MDC	All

PROBLEM

The tire label on the above mentioned vehicles is not the correct one.

SOLUTION

Replace the tire label.

PART REQUIRED

Order part through regular channel.

PART DESCRIPTION	PART NUMBER
Tire label	704 902 334

A WARNING					
COLD tire pressure:		Improper tire pressure can increase the risk of loss of control.			
	FRONT: 83 kPa (12 psi)	 An underinflated tire can come off the rim. Use Max pressure if total load exceeds 180 kg (400 lb), including operator, passenger, cargo, accessories, and trailer tongue weight. 			
704902334C					

PROCEDURE

Heat label for a few seconds with a heat gun.

Remove label.

Clean surface using isopropyl alcohol.

Install new tire label at the same location as the previous label.

WARRANTY

Submit a warranty claim using the normal claiming procedure. For claiming procedure, refer to the *DEALER/DISTRIBUTOR WARRANTY GUIDE*.

CAMPAIGN NUMBER	2013-9
Claim type	Campaign claim
Action	Repair
Flat rate	0.3 hour
Expiration date	January 31, 2016