




WARRANTY
CAMPAIGN

**SIDE-BY-SIDE
VEHICLES**

**WARRANTY
Bulletin**



CAUTION: All involved customers must be notified, all involved units must be corrected as per instructions herein.

Campaign no.: 2013-11

September 30th,
2013

Subject: **Vehicle Control Module (VCM) Reflash**

No. **2013-6**

REVISION 1

September 30, 2013

YEAR	MODEL	MODEL NUMBER	SERIAL NUMBER
2013	Commander™ Electric	All	All

******* OBSOLETE *******

Use the Warranty Bulletin 2013-8

PROBLEM

The Vehicle Control Module (VCM) calibration file may be corrupted which may lead to the following problems:

- Vehicle will stop working
- E will be displayed in the gauge instead of the gear position (P, R, N, H, L)
- No communication will be possible with the VCM using the diagnostic tool.

SOLUTION

Re-flash the Vehicle Control Module (VCM).