



# WARRANTY CAMPAIGN

## WATERCRAFT WARRANTY Bulletin



**CAUTION:** All involved customers must be notified, all involved units must be corrected as per instructions herein.

Campaign no.: 2010-0004

May 21, 2010

Subject: **Parts Missing in the PDI Kit**

No. **2010-4**

YEAR	MODEL	MODEL NUMBER	SERIAL NUMBER
2010	GTI	23AB	See list enclosed

## PROBLEM

On some of the above described vehicles, the reverse handle guide is missing in the PDI kit.

## SOLUTION

Order a supplement kit in order to complete the PDI kit.

## PARTS REQUIRED

DESCRIPTION	P/N	QUANTITY
Supplement kit	(P/N 294 000 922)	1

## WARRANTY

Submit a warranty claim using the following information:

Warranty will pay for parts and part ordering time.

## Warranty Information

CAMPAIGN NUMBER	2010-0004
Claim Type	Campaign Claim
Action	Order kit
Flat Rate Time	0.1 hour

---

# **SERIAL NUMBER LISTING OF INVOLVED WATERCRAFT**

***Model: 23AB***

From 026876 to 026950

From 027686 to 027784

From 028278 to 028488

From 029575 to 029773

From 030581 to 030676

From 031145 to 031196