



BRP Utility and Diagnostic Software

Bulletin



November 10, 2009 Subject: New Version of B.U.D.S. (P2.3.27.7)

No.

N/A

YEAR	MODEL	MODEL NUMBER	SERIAL NUMBER
2010	Can-Am™ Roadster	A3AA, A3AB, A3AC, A4AA, A4AD, A7AA, A7AC, A7AD, A7AF, B5AA, B5AB, B5AC, B5AD, B5AE, B5AG	All

## **GUIDELINES**

This B.U.D.S. version is for the Can-Am Roadster RT models only. It is now available on BOSSWeb, go to:

- www.bossweb.brp.com
- ComCenter = Document
- Document Type = Diagnostic Software
- Select the following version

## **VERSION P2.3.27.7**

**NOTE:** This version of B.U.D.S. was specifically designed for the Can-Am Roadster RT models. Can-Am Roadster GS and all other product lines still require the use of P2.3.26.

Always use the latest version of B.U.D.S. when programming or troubleshooting any product line vehicle that is included in this update.

Refer to the following table to know the new version features.

PRODUCT LINES	INVOLVED	FEATURES
Can-Am Roadster	>	MY2010 RT model only

## B.U.D.S. SOFTWARE INSTALLATION

Proceed with the regular installation procedure for all products.

If you are not familiar with B.U.D.S. or how to install it please go to:

- www.bossweb.brp.com
- ComCenter = Document

- Document Type = Diagnostic Software
- Select the following document

B.U.D.S. Program Installation Instructions