



Published Bulletin 2004

updated 15/12/2006

Publication Type	Bulletin No.	Subject	Campaign No.	Model Year	Model Name	Safety	Revision
Warranty bulletin	2004-2	Access Cover Hinge	2004-0004	2004	RXP	Safety Recall	
Warranty bulletin	2004-3	A) Rear View Mirrors B) Fire Extinguisher Holder	2004-0003	2004	RXP		
Warranty bulletin	2004-1	Intake Manifold Bolts	2004-0002	2004	GTI RFI, GTI LE RFI		
Warranty bulletin	2004-4	A) RXP Recalibration & Knock Sensor Update B) Storage Cover Stud Rework	2004-0005	2004	RXP A Green, RXP Yellow, RXP Yellow (International)		
Warranty bulletin	2004-5	Safety Lanyard Malfunction	2003-0001, 2004-0007	2003, 2004	GTI (717)	Safety Recall	
Service bulletin	2006-13	Service Tools		ALL	ALL		
Service bulletin	2004-18	Storage procedure (4 TEC engine units)		2004	GTX; GTX wake; GTX supercharged; RXP		Rev. 1
Service bulletin	2004-19	Storage procedure (2-stroke engine units)		2004	3D RFI; GTI/ GTI RFI; GTI LE/ GTI LE RFI ; XP DI		
Service bulletin	2006-3	Importance of PDI		ALL	ALL		
Service bulletin	2004-9	Fuel Pump Inlet Filter		2004	see list on bulletin		
Service bulletin	2004-16	Supercharger Slip Clutch Specs		2003, 2004	All Supercharged (BV) and Supercharged Intercooled (BV IC) Models		
Service bulletin	2004-17	Front Bumper Installation		2004	ALL		

Service bulletin	2004-15	A) 4-TEC Starter Drive Replacement B) 4-TEC Valve Guide and Valve Stem Seal Replacement		2002;2003; 2004	ALI 4-TEC Engines		Revision 1
Service bulletin	2004-101	2004 Operator's Guide Update		2004	GTX 4-TEC, GTX 4-TEC WAKE, GTX 4-TEC SUPERCHARGED, GTX 4-TEC LTD SUPERCHARGED, RXP		
Service bulletin	2004-11	New Service Tools		2004	All		
Service bulletin	2004-4	Paint Codes		2004	All		1
Service bulletin	2004-5	B.U.D.S. Version		2004	ALL		
Service bulletin	2004-6	French Decal Kit		2004	All		
Service bulletin	2004-7	Quick Reference for 4-TEC Jet Pumps		2002, 2003, 2004	GTX 4-TEC, GTX 4-TEC WAKEBOARD, GTX 4-TEC SUPERCHARGED, GTX 4-TEC LTD SUPERCHARGED		
Service bulletin	2004-8	Mirror to be installed at PDI		2004	GTI LE, GTI LE RFI, GTX 4-TEC, GTX 4-TEC WAKEBOARD EDITION, GTX 4-TEC SUPERCHARGED, GTX 4-TEC LIMITED SUPERCHARGED		
Service bulletin	2004-10	Canadian Coast Guard Compliance Label		2004	GTI/GTI RFI/GTI LE/GTI LE RFI/XP DI/GTX 4-TEC/GTX 4-TEC WAKE/GTX 4-TEC Supercharged/GTX 4-TEC LTD Supercharged/RX/3D		
Service bulletin	2004-12	O.P.A.S. Maintenance Information		2002, 2003, 2004	GTX 4-TEC, GTX, GTX DI, GTI, GTI LE, GTI LE RFI		
Service bulletin	2004-13	MPEM Adaptor Installation / Revision 1		All	All DESS equipped compatible with portable MPEM programmer		1
Service bulletin	2004-14	Battery Care Reminder		2004	All		
Service bulletin	2004-3	High Altitude		2004	All		Rev. 1
Service bulletin	2004-1	Oil Application for 4-TEC Engines		2004	GTX 4-TEC, GTX 4-TEC Supercharged, GTX 4-TEC Limited Supercharged, GTX 4-TEC Wakeboard Edition, RXP		
Service bulletin	2004-2	Impeller Chart		2004	All		
Predelivery bulletin	2004-102	All GTX 4-TEC (International)		2004	All GTX 4-TEC		Revision 1
Predelivery bulletin	2004-101	GTI and GTI LE (International)		2004	GTI and GTI LE		Revision 1
Predelivery bulletin	2004-2	Predelivery		2004	GTI, GTI LE		
Predelivery bulletin	2004-103	RXP (International)		2004	RXP		Revision 1
Predelivery bulletin	2004-104	2-TEC DI Models (International)		2004	XP DI		
Predelivery bulletin	2004-106	3D RFI		2004	3D RFI		
Predelivery bulletin	2004-105	2-TEC RFI Models		2004	2-TEC RFI		Revision 1
Predelivery bulletin	2004-103	RXP (International)		2004	RXP		Revision 1
Predelivery bulletin	2004-104	2-TEC DI Models (International)		2004	XP DI		
Predelivery bulletin	2004-106	3D RFI		2004	3D RFI		
Predelivery bulletin	2004-105	2-TEC RFI Models		2004	2-TEC RFI		Revision 1
Check list	2004 Check List	Predelivery		2004	Sea-Doo		

Published Bulletin 2005

<b>Publication Type</b>	<b>Bulletin No.</b>	<b>Subject</b>	<b>Campaign No.</b>	<b>Model Year</b>	<b>Model Name</b>	<b>Safety</b>	<b>Revision</b>
Warranty bulletin	2005-1	Non Conforming Serial Number	2005-0001	2005	GTX 4-TEC WAKE		
Warranty bulletin	2005-2	GTI 717 - Resonator Strap	2005-0002	2005	GTI 717		
Service bulletin	2006-13	Service Tools		ALL	ALL		
Service bulletin	2005-7	Transport Canada - Safety and Security - Office of boating Safety Compliance Labels		2005	All		
Service bulletin	2005-8	Lanyards Recognition during PDI		2005	All (except GTI™ / GTI LE with 717 engine)		1
Service bulletin	2005-9	Supercharger Repair Kits		2003 TO 2005	1503 engines SC and SCIC		
Service bulletin	2005-10	Storage Procedure for 4 TEC Engine Equipped Vehicles		2005	All 4 TEC engine equipped vehicles		Revision 1
Service bulletin	2005-11	Storage procedure for 2-Stroke Engine Equipped Vehicles		2005	3D tm RFI, GTI tm, GTI RFI, GTI LE		Revision 1
Service bulletin	2006-3	Importance of PDI		ALL	ALL		
Service bulletin	2005-12	Glued Decks Mats Replacement Procedure		2005	All		
Service bulletin	2005-13	Pre-Season/Annual Safety inspection (at owner expense)		2005	All		
Service bulletin	2006-11	New Optional Service Tools		All	All		
Service bulletin	2005-1	Impeller Chart		2005	All		
Service bulletin	2005-2	Paint codes & gelcoat		2005	ALL		1
Service bulletin	2005-3	New Service tools		2005	ALL		
Service bulletin	2005-4	New B.U.D.S. Version: 2.3.0		2005	All		
Service bulletin	2005-5	GTI RFI Base Models Fault Codes		2005	GTI RFI Base		
Predelivery bulletin	2005-102	Predelivery Inspection GTI (Carbureted)		2005	GTI™		
Predelivery bulletin	2005-103	Predelivery Inspection 2-TEC RFI		2005	GTI™ RFI / GTI LE RFI		Rev. 1
Service bulletin	2005-5	GTI RFI Base Models Fault Codes		2005	GTI RFI Base		
Predelivery bulletin	2005-102	Predelivery Inspection GTI (Carbureted)		2005	GTI™		
Predelivery bulletin	2005-103	Predelivery Inspection 2-TEC RFI		2005	GTI™ RFI / GTI LE RFI		Rev. 1
Predelivery bulletin	2005-104	Predelivery Inspection		2005	3D		Revision 1
Predelivery bulletin	2005-101	Predelivery Inspection All 4-TEC		2005	GTX 4-TEC; GTX 4-TEC Wake; GTX 4-TEC Limited; RXT; RXP		
Check list	Check list	Check list		2005	All models		



Warranty bulletin	2006-1	Fuel System Check Valve Cracking	2006-0001	2006	RXP, RXT, GTI SE, GTI	Safety Recall	Rev. 1
Warranty bulletin	2006-2	Storage Bin Lid Hinge Breaking Off and Storage Cover Stiffener Separation	2006-0002	2006	GTI SE		1
Service bulletin	2006-11	New Optional Service Tools		All	All		
Service bulletin	2006-10	New Version of B.U.D.S. : 2.3.8		2006	All		
Service bulletin	2006-8	Premium Gauge Compass Feature		2006	GTX, RXP and RXT Series		
Service bulletin	2006-9	MPI-2 Hardware for B.U.D.S.		2006	See Bulletin		
Service bulletin	2006-12	My 2006 1503 4-tec Run-Ability Issue		2006	All with any 1503 4-Tec Tm Engine		
Service bulletin	2006-13	Service Tools		ALL	ALL		
Service bulletin	2006-14	GTI Wind Deflector		2006	GTI tm		
Service bulletin	2006-15	Storage Procedure for 4-TEC tm Engine Equipped vehicles		2006	All		
Service bulletin	2006-16	Storage Procedure		2006	3D DI		
Service bulletin	2006-2	Carbon Monoxide (CO) Warning Label Installation (California Only)		2006	All		
Service bulletin	2006-3	Importance of PDI		ALL	ALL		
Service bulletin	2006-1	Impeller Chart		2006	All		
Service bulletin	2006-4	New Version of B.U.D.S 2.3.7: P1607 Fault Code		2006	All		
Service bulletin	2006-5	High Altitude		2006	All		
Service bulletin	2006-7	Transport Canada-Safety and Security-Office of Boating Safety-Compliance Labels		2006	All		
Service bulletin	2006-6	Paint Codes & Gelcoat		2006	All		Revision 1
Predelivery bulletin	2006-2	Pre delivery Inspection		2006	3D		
Predelivery bulletin	2006-1	Pre delivery Inspection (4 TEC) (North America / International)		2006	GTX, GTX SC, GTX Limited, RXT, RXP, GTI SE, GTI std, STI Std R		Revision 3
Service bulletin	2006-7	Transport Canada-Safety and Security-Office of Boating Safety-Compliance Labels		2006	All		
Service bulletin	2006-6	Paint Codes & Gelcoat		2006	All		Revision 1
Predelivery bulletin	2006-2	Pre delivery Inspection		2006	3D		
Predelivery bulletin	2006-1	Pre delivery Inspection (4 TEC) (North America / International)		2006	GTX, GTX SC, GTX Limited, RXT, RXP, GTI SE, GTI std, STI Std R		Revision 3
Check list	Check list	Predelivery Check list		2006	All models		



**Published Bulletin 2007**

updated 15/12/2006

Service bulletin	2006-11	New Optional Service Tools		All	All		
Service bulletin	2006-13	Service Tools		ALL	ALL		

Service bulletin	2007-2	Importance of PDI		2007	ALL		