


COLOR TABLE

WH = WHITE	BK = BLACK
RD = RED	YL = YELLOW
VI = VIOLET	BE = TAN
GN = GREEN	BR = BROWN
GY = GREY	BU = BLUE
PK = PINK	OR = ORANGE



FUSE BOX DECAL (FB1)

30A RELAY	5A 15A	3A 10A	3A 10A	30A 30A	30A 30A	30A 30A
+12 VOLTS ACCESSORY	+12 VOLTS		+12 VOLTS			
+12 VOLTS ACCESSORY						
10. 3A	11. 3A	12. 3A	13. 10A	14. 10A	15. 10A	16. 5A
DEPTH SOUNDER	DEPTH SOUNDER	DEPTH SOUNDER	START/STOP	START/STOP	START/STOP	START/STOP
COMMUNICATION (CAN HI)			COMMUNICATION (CAN LOW)			
+12 VOLTS ACCESSORY			GROUND			