


**WARRANTY**  
CAMPAIGN**ATV**  
**WARRANTY**  
Bulletin**CAUTION:** All involved customers must be notified, all involved units must be corrected as per instructions herein.

Campaign no.: 2009-0001

May 30<sup>th</sup>, 2008Subject: **A) Operator's Guide**  
**B) Missing Mirrors**  
— **European Community Only**—No. **2009-1**

YEAR	MODEL NAME	MODEL NUMBER	SERIAL NUMBER
2009	DS 450™ (European Community)	3F9G / 3G9D	All

NOTE: This bulletin applies to vehicles meant for the **European Community only**.

## PROBLEM "A"

An inaccurate English version of the Operator's Guide has been placed in the crate with the above-mentioned vehicles; the guides in other languages are correct.

## SOLUTION "A"

When getting vehicle ready for delivery, discard existing Operator's Guide and replace it by the good one.

For languages other than English, refer to local sources including the web-site, ([www.operatorsguide.brp.com](http://www.operatorsguide.brp.com)). The English version on the site has also been corrected.

NOTE: Make sure to give the Operator's Guide to the customer as specified in PDI Bulletin and PDI Check List.

## PART REQUIRED "A"

DESCRIPTION	P/N	QTY
English Operator's Guide	219 000 590	1

Order part, as required, through regular channel.

## PROBLEM "B"

Mirrors, that are mandatory on European Community vehicles, were not included in the crate with the above-mentioned vehicles.

## SOLUTION "B"

When getting vehicle ready for delivery, order left side and right side mirrors and install them as described in the PDI bulletin.

## PARTS REQUIRED "B"

DESCRIPTION	P/N	QTY
Left Side Mirror	709 400 406	1
Right Side Mirror	709 400 523	1

Order parts, as required, through regular channel.

## WARRANTY

Submit a warranty claim using the following information.

WARRANTY INFORMATION	
Campaign Number	2009-0001
Claim Type	Campaign Claim
Flat Rate	Part(s) Only, no labor involved (PDI item)

For claiming procedure, refer to the *Dealer/Distributor Warranty Guide*.